


INSTRUCTIONS TO CONVERT AN HP CP1215/1515/1518/CM1312MFP OEM CARTRIDGE TO FIT AND USE IN AN HP CP1525/CM1415 PRINTER

OEM HP CP1215/1515/1518/CM1312MFP CARTRIDGE (CB540A/CB541A/CB542A/CB543A)



T.P.E. CC1671 HP CP1525/CM1415 OUTER LEFT END CAP



T.P.E. CC1672 HP CP1525/CM1415 OUTER GEAR SIDE RIGHT END CAP



Procedures



Step 1.
Remanufacturing the OEM HPCP1215/1515/1518/CM1312MFP Cartridge as normal standard procedure.



CC1671 on the HP CP1215/1515/1518/CM1312 MFP Cartridge.

CC1672 on the HP CP1215/1515/1518/CM1312 MFP Cartridge.

Step 2.
Disregard the OEM Left and Right End Cap of the HP CP1215/1515/1518/CM1312 MFP. Replace them with TPE CC1671 and CC1672 Left and Right End Cap. Install the chips onto the End Cap.

The conversion for HP CP1525/CM1415 is now complete.